

Bulletin: #16-06
 Date: 12/21/2016 Revised: 04/19/2017

HVAC CLEANERS

All requirements set forth in this Technical Bulletin supersede those in Technical Bulletin 13-05.

Cleaning rooftop air conditioning units is necessary maintenance, but the use of incompatible cleaners can potentially be harmful to a Duro-Last® roof. Building and HVAC maintenance personnel should be informed to use only cleaners that are compatible with the roof system.

Below are two lists of cleaners that have been tested for compatibility with Duro-Last membranes. Compatibility testing is based on each product's current chemical formulation.

If a particular cleaner is being used and is not shown, please discontinue using the cleaner and send a sample to Duro-Last to verify compatibility.

INCOMPATIBLE CLEANERS	
MANUFACTURER	PRODUCT NAME
Nu-Calgon	Evap Pow'r®-C *
Nu-Calgon	CalClean® *
Nu-Calgon	Nu-Brite® *
DuBois	Double-Cut Topaz™ *
Zep®	Orange Gel Degreaser *
DiversiTech®	Triple-D™ Universal Coil Cleaner *
RectorSeal® Corporation	Renewz™ Coil Cleaner *
Atlantic Chemical Equipment Company	Super Degreasing Solvent *
Atlantic Chemical Equipment Company	Foam n' Clean Coil Cleaner *

COMPATIBLE CLEANERS	
MANUFACTURER	PRODUCT NAME
Atlantic Chemical Equipment Company	Super Klean® Cleaner/Degreaser *
Atlantic Chemical Equipment Company	Evap-Klean Plus *
DiversiTech®	Pro-Green™ Self-Rinsing Evaporator Coil Cleaner *
SELIG Industries	BGT Coil Cleaner *
Alberson's	Roof Tile Cleaner RTC 5000 *
Spic and Span®	Multi-Surface & Floor Cleaner *
Simple Green®	Industrial Cleaner & Degreaser *

* Remove any remaining cleaners from the Duro-Last membrane by thoroughly rinsing with water. Excess water must be mopped and disposed of properly. Always use as directed on product labels and follow all disposal procedures.

If you have any questions regarding this Technical Bulletin, please contact Duro-Last at 800-248-0280.